

The driver installation package **PC-USB\_IMB-MDU\_inst.exe** installs the PC-usb / IMB-mdu driver. This driver is required to operate the following devices :


- PC-usb ( F601 020 / F601 021 )
- 3i-usb ( F420 010 )
- IMB-mdu ( F120 110 )
- IBRit-md1-usb ( F101 010 )

The driver installation package is located on the CD-ROMs ,*IBR Support Software* and ,*Software for Metrology and SPC* in the directory <CDROM>:\USB-Driver\PC-USB\_IMB-MDU\PC-USB\_IMB-MDU\_inst.exe.

The most recent version can be downloaded at [http://www.ibr.com/download/PC-USB\\_IMB-MDU\\_inst.zip](http://www.ibr.com/download/PC-USB_IMB-MDU_inst.zip) .


## 1.

When the driver installation package is started, the installer asks for a directory where the driver files should be copied to :



## 2.

By clicking on Next, the installer copies the required files to the directory selected and automatically opens the Device Driver Installation Wizard :



## 3.

